





## ENGINEERING DRAWING MODELS



Cussons Models for Engineering Drawing are used in Drawing Offices and Schools all over the world and are of great value in teaching Drawing. The Models are extremely well made, light and accurate and are painted to denote the various materials. The Models are available in sets as indicated or may be ordered from the lists of titles in this leaflet, all of which are illustrated.



## ENGINEERING DRAWING MODELS







Models 41 to 80 (Product Numbers P1041-P1080)

P1001 Eccentric and Sheave with Bolts  
P1002 Simple Bearing Housing (37 mm)  
P1003 Split Bearing with separate shells  
P1004 Thrust Bearing  
P1005 Assembly with Key and Slotted Keyway  
P1006 Assembly with Saddle Key  
P1007 Staking on  
P1008 Taper Pin through Collar  
P1009 Side Pin to allow rotation  
P1010 Crane Hook  
P1011 Overhung Crankpin and Shaft  
P1012 Foundation Bolt  
P1013 Pump Rod Joint  
P1014 Gib and Cotter Joint in Section  
P1015 Flanged Pipe Joint  
P1016 Gland and Stuffing Box with bolts  
P1017 Piston with rings and part piston rod and nut  
P1018 Poppet Valve with seating  
P1019 Angle Section Steel  
P1020 Tee Section Steel  
P1021 Channel Section Steel  
P1022 I Section Steel  
P1023 Box Coupling and part of shaft  
P1024 Crosshead with slide blocks  
P1025 Single Rivetted Lap Joint  
P1026 Double Rivetted Lap Joint  
P1027 Single Rivetted Butt Joint  
P1028 Rivetted Angle Fabrication  
P1029 Wall Bracket (for No. 3)  
P1030 Ragbolt (25 mm) with nuts  
P1031 Slide Valve with spindle and nuts  
P1032 Knuckle Joint  
P1033 Rivetted Joint with 5 rivet forms  
P1034 Thread Form – ISO metric  
P1035 Thread Form – Buttress  
P1036 Thread Form – Square  
P1037 Bolt, Nut and Washer  
P1038 Connecting Rod End with Cotter  
P1039 Spur Wheel  
P1040 Pulley

**Models may be ordered individually**

P1041 Flange Coupling with bolts and nuts  
P1042 Clevis Joint with pin  
P1043 Connecting Rod End with Gibs and Cotter  
P1044 Double Rivetted Butt Joint  
P1045 Crankshaft – Flat Webs  
P1046 Belt Pulley – grooved  
P1047 Wall Bracket (for No. 3)  
P1048 Overhung Crank with pin  
P1049 Connecting Rod Eng  
P1050 Connecting Rod – complete  
P1051 Big End Assembly  
P1052 Flanged Pipe Joint  
P1053 Fusible Plug in section  
P1054 Bevel Gear  
P1055 Axle Bearing  
P1056 Crankshaft with Balance Weights  
P1057 Lubricator  
P1058 Cover – internally ribbed  
P1059 Needle Lubricator  
P1060 Bearing Bracket  
P1061 Port Face (for No. 31)  
P1062 Knuckle Joint  
P1063 Cam  
P1064 Bell Crank Lever – unequal arms  
P1065 Radius Link  
P1066 Bearing Shells with location  
P1067 Tool Holder  
P1068 Loose Collar with setscrew  
  
P1069 Sectional Box – to illustrate necessity of sections  
P1070 Capstan Handle  
P1071 Stanchion  
P1072 Bracket for Shaft  
P1073 Box Spanner  
P1074 Ratchet Wheel  
P1075 Gland Bearing  
P1076 Lathe Quadrant  
P1077 Crankshaft – circular webs  
P1078 Flanged Pulley and Spindle  
P1079 Gland with oil feed  
P1080 Hanger for Shaft Bearing  
  
P1085 The 40 Set. Models P1001-P1040 inclusive  
P1086 The 80 Set. Models P1001-P1080 inclusive  
P1087 The 12 Set. Models P1069-P1080 inclusive